






SETTING THE HEIGHT OF THE SENSOR IS INEFFICIENT AND TIME-CONSUMING.




THE BOLTS UNDERNEATH THE SENSOR ARE DIFFICULT TO ACCESS AND MORE TIME TO REMOVE. TIGHTENING OF THE BOLTS CAN ACCIDENTALLY SHIFT THE HEIGHT OF THE SENSOR.



ADJUSTMENT AVOIDING ERRORS.

USING THE Z-AXIS STAGE, WORK IS DONE EFFICIENTLY IN A SHORT PERIOD OF TIME.



SCALE PLATES BESIDE THE HANDLE.

CHARACTERISTICS OF THE Z-AXIS STAGE (ZJK-90)

