







Some defects are overlooked when inspecting using a magnifying glass.






Since the appearance of the cracks is different depending on the angle of view of the workpiece when seen through the magnifying glass, and the difference in the detecting ability among workers becomes evident, leading to a variation in the quality.



Features of Inspection Microscope Measure Scope [M-1 (A)]



Posseses bright lenses